

TABLE OF CONTENTS

– DOCUMENTS	·
1. – Cover Page	»
2. – Statement	»
3. – Table of Contents	»
4. – Introduction	»
5. – Guide for CAP	»
6. – Executive Summary	»
7. – Ship Description	»
8. – Structural Condition Assessment Report	»
9. – Hull Survey Report	»
9.1. – Main Parts	·
9.2. – Ballast Tanks	·
9.2. – Other Spaces	·
11. – Machinery Survey Report	»
11.1. – Main Engine	»
11.2. – Propulsion, Shafting and Steering System	»
11.3. – Auxiliary Engines and Generators, Main Electrical Consumers	»

11.4. – Electric Switchboard >>

11.5. – Fuel Oil System >>

11.6. – Lubricating Oil System >>

11.7. – Cooling Water System >>

11.8. – Fire Pumps >>

11.9. – Compressed Air System >>

11.10. – Records >>

11.11. – Safety protection devices >>

11.12. – Cargo Gear Appliances >>

11.13. – Other pumps >>

11.14. – Hydraulic units >>

12. – Ship Status >>

13. – Thickness Measurements Report >>

– ANNEXES .

– REFERENCES .

[1] – RINA - Rules for the classification of Ships - Part B 'Hull and Stability' .

[2] – RINA - Guide for the Ship Condition Assessment Programme (CAP) .



TETHYS SUPPORTER

IMO no. 8741765

13-Feb-2019